

		DMINISTRATIVE DETAILS	
Mark Number	753291	_	
Alternate Names	ROBI	Town	
	ROBINA SUNPOZ ROBINA	Local Authority	GOLD COAST CITY
Levelit Description	NRW BUILDING (ROBIN		
Locality Description Related Information		A) BOLT ON A STEEL BRACKET FI	
iverated information	BUILDING ROOF.	JOET ON A STELL BRACKET FI	ALD TO A STELL BEAM ON A
	CORS METAL MARK ON		
Mark Type Installed By	NRM	Last Visited	26-Oct-2022
Installed By	01-Nov-2005	Sketch Available	26-001-2022 No
Mark Condition	GOOD	Num Connections	2
		Null Comediate	-
		GDA2020 COORDINATES	
Lineage	Datum		
Reg13 Certificate	https://ga-gnss-products-v1.s3.amazonaws.com/public/reg13/ROBI.pdf		
	Refer to the Reg13 Certi	ficate for the current authoritation	ve position.
Latitude	28º 04' 37.04413" S	MGA2020 Easting	537459.767m
Longitude	153º 22' 52.52983" E	MGA2020 Northing	6894214.033m
Hrz Posn Uncertaint	y 0.011m	MGA2020 Zone	56
Ellipsoidal Height	65.156m	MGA2020 Point Scal	e 0.99961732
Vrt Posn Uncertainty	0.021m	MGA2020 Grid Conv	0º 10' 46"
Published	06-Feb-2023	Fixed By	GPS
Adjustment	REGULATION 13 CERTI	FICATE 23.02	
	GDA94 1	TRANSFORMED COORDINATES	
Latitude	28° 04' 37.08919" S	MGA94 Easting	537459.181m
Longitude	153º 22' 52.50853" E	MGA94 Northing	6894212.649m
Ellipsoidal Height	65.258m	MGA94 Zone	56
		AHD HEIGHT	
Lineage	Derived		
Height	25.088m	Vertical Uncertainty	Class D / 5th ORDER
Published	04-Nov-2013	Fixed By	GPS
Origin Mark		NLN Section	
Source	REGULATION 13 CERTI	FICATE 2013	
	Model: AUSGEOID09 IN	TERPOLATED / N Value: 40.204r	n
		SURVEY CONNECTIONS	
SP316142 2	6-Oct-2022	SURVEY CONNECTIONS	

The State of Queensland (Department of Resources) 2024. The State does not warrant that the copyright information provided to the client by this system is free from error. The State shall not be liable for any loss, damage or injury suffered by the client or any other person by the client's use of the copyright information.