

Survey Control Mark Report

ADMINISTRATIVE DETAILS Town

Mark Number 753291

ROBI Alternate Names

ROBINA Local Authority GOLD COAST CITY

SUNPOZ ROBINA

Locality Description NRW BUILDING (ROBINA)

Datum

Related Information MARK S A THREADED BOLT ON A STEEL BRACKET FIXED TO A STEEL BEAM ON A

BUILDING ROOF.

Mark Type CORS METAL MARK ON POOF ON BUILDING

NRM 26-Oct-2022 Installed By Last Visitad Installed Date 01-Nov-2005 Sketch Available

Nο Mark Condition GOOD Num Connections 2

GDA2020 COORDINATES

Lineage Reg13 Certificate https://ga-gnss-products-v1.s3.amazonaws.com/public/reg13/ROBI.pdf

Refer to the Reg13 Certificate for the current authoritative position.

289 041 37 04413" S MGA2020 Easting 537459 767m Latituda

1539 22' 52 52983" F 6894214 033m Lonaitude MGA2020 Northing MGA2020 Zone 56 Hrz Posn Uncertainty 0.011m

Ellipsoidal Height 65.156m MGA2020 Point Scale 0.99961732 MGA2020 Grid Copy 09 10' 46" Vrt Posn Uncertainty 0.021m

Published 06-Feb-2023 GPS Fixed By

REGULATION 13 CERTIFICATE 23 02 Adjustment

GDA94 TRANSFORMED COORDINATES

289 041 37 08919" S MGA94 Easting 537459 181m Latituda

1539 22' 52 50853" F MGA94 Northing 6894212.649m Longitude

Ellipsoidal Height 65 258m MG494 Zone 56

AHD HEIGHT

Dorived Lineage 25 088m

Height Vertical Uncertainty Class D / 5th ORDER

Published 04-Nov-2013 Fixed By GPS REGULATION 13 CERTIFICATE 2013

Origin Mark NI N Section

Model: AUSGEOID09 INTERPOLATED / N Value: 40.204m

SURVEY CONNECTIONS

SP316142 26-Oct-2022 SP301120 30-Aug-2018

Source

@ The State of Queensland (Department of Resources) 2024. The State does not warrant that the copyright information provided to the client by this system is free from error. The State shall not be liable for any loss, damage or injury suffered by the client or any other person by the client's use of the copyright information.

Report created 28-Nov-2024 Page 1 of 1